







LAMA Minibus Damage Record

31 Mar 24



Key:

 Major Dent	 Minor Crease Dent/Scuff	 Paintwork Damage
--	---	---