







# LAMA Minibus Damage Record

11 May 22



Key:

 Major Dent	 Minor Crease Dent/Scuff	 Paintwork Damage
--	---	---